## COTTON MOISTURE METER

#### MS7100C

VER170D08

Thanks for choosing our moisture meters! For your easy to master this instrument as soon as possible, please read following instructions carefully and always keep this meter within easy reach.

- canceled.
- 4.4 Replace batteries

Cotton moisture meter MS7100C is a professional cotton moisture meter, it can testing cotton lint, cotton seed. It applicable of cotton collection, processing and other relevant industry.

Automatic temperature

Compensation

4x1.5 AAA size (UM-4) battery

140mm×60mm×22mm

175mm×40mm×20mm

175g (not including batteries)

Power supply:

Dimensions:

Guarantee: 1 year

150mm(optional)

Main Unit:

Weight:

Pin: 80mm

#### 1.FEATURES

- 1.1 It is portable, compact, easy to use and the moisture measurement readings are instant.
- 1.2 Digital display with back light gives exact and clearly reading although you stay at the somber conditions.
- 1.3 It will save time and expense by monitoring dryness and helps to prevent deterioration & decay caused by moisture whilst in storage, therefore processing will be more convenient and efficient.
- 1.4 The moisture meter operates by electrical

conductivity and has automatic temperature compensation.


- 1.5 Manual off at any time. Auto power off after 5 minutes from last operation.
- 1.6 Data hold function. Low battery alert.

#### 2.SPECIFICATION

Display: 4 digital LCD Measuring range: 5-45% Operating conditions: Temperature: 0-60°C Humidity: 5%-90%RH Resolutions: 0.1 Accuracy: ± 0.5%n Operating principle:

Electrical conductivity,

### 3.PANEL DESCRIPTIONS



- 1-1 Buzzer 1-2 % symbol
- 1-6 Testing value 1-7 Warning light
- 1-3 Low battery 1-8 Function key 1-4 Max symbol 1-9 Zero/inc key 1-5 Testing symbol 1-10 Backlight key

will be returned back the factory setting, just to say, AL1=13,AL2=18.

1-11 Battery cover 1-14 Hold/dec key 1-12 Probes cover 1-15 Power key 1-13 Testing probes

# 4.OPERATION PROCEDURE

- 4.1 Turn on the power (6) key, the symbol "0.0" will be showed on display. It will need zeroing if showed other value, please depress key while the probe sensor without touch anything, or zeroing is not efficient. Zeroing can decrease the effect from the temperature and humidity in the air.
- 4.2 Hold the instrument with your hand, then take off the cover of the sensor

### Notes:

Please take out the batteries if the instruments without use for a long time.

Put the probe in the air without touch anything when zeroing, or the zeroing is not efficient.

and insert the probes into the materials straightly, the probes are more deeper, the value is more accurate.

- 4.3 Depress 🕳 key, the symbol "max" will be showed on display, then the max value must be stored on display when measuring process. Depress the key again, this function will be
- When battery symbol showed on display, it must replace the batteries in time. Slide the batteries

cover ,put the batteries into the hole correctly.

## **5.WARNING SETTING**

- 5.1 Depressing key (FUN) and don't release until "AL2" showed on display(it will takes 5 seconds to complete operation), then press " ( )" key or "a" key to choose your suitable value according to your needs, press FUN key again back to the operation state.
- 5.2 Setting the "AL1" just the same ways as "AL2".
- 5.3 Usually ,"AL2"must larger than "AL1", if the "AL2" less than "AL1" during setting process, then the instrument